

09/588050

Patent No. 6,324,082
Customer No. 24498

RCA 89098

**RECEIVED
CENTRAL FAX CENTER**

JUL 12 2007

Certificate

JUL 13 2007

of Correction

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicant : Anton Werner Keller
Patent No. : 6,324,082
Issued : November 27, 2001
For : MAINS FREQUENCY SYNCHRONOUS BURST MODE POWER SUPPLY
Examiner : Adolf D. Berhane
Art Unit : 2838

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner of Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Attn: Certificate of Correction Branch

Sir:

It is respectfully requested that a Certificate of Correction be issued under the provisions of Rule 322 to correct errors in the above-identified patent. The corrections to be made are stated on the enclosed PTO/SB/44 form.

It will be noted by comparing the issued patent 6,324,082 with the application (Serial No. 09/588,050) as it was allowed, that the errors occurred in the printing of the patent and were not due to the fault of applicant. Accordingly, it is respectfully requested that a Certificate of Correction be issued as indicated on the enclosed PTO/SB/44 form.

CERTIFICATE OF TRANSMISSION

I hereby certify that this correspondence is being facsimile transmitted to the United States Patent and Trademark Office, Fax No. (571) 273-8300 on:

July 12, 2007
Date

Lori Klewin
Lori Klewin

JUL 16 2007


Patent No. 6,324,082
Customer No. 24498

RCA 89098

Please charge any fees related to this request to Deposit Account 07-0832.

Respectfully submitted,

By:



Jeffrey D. Hale
Reg. No. 40,012
(609) 734-6444

Enclosure (Form PTO/SB/44)

Patent Operations
Thomson Licensing LLC
P. O. Box 5312
Princeton, NJ 08543-5312

JUL 16 2007

PTO/SB/44 (07-03)

Approved for use through 01/31/2004. OMB 0651-0033

U.S. Patent and Trademark Office: U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 6,324,082

DATED : November 27, 2001

INVENTOR(S) : Anton Werner Keller

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

In Column 7, Line 1, please delete "2" and insert therefor --12--.

MAILING ADDRESS OF SENDER: Joseph J. Laks, Vice President, Patent Operations
Thomson Licensing LLC
P. O. Box 5312, Princeton, NJ 08543-5312

PATENT NO. 6,324,082

No. of additional copies



Rev. 01/17/2007

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

2007 10 2007